

G. COMMERCIAL MOTOR VEHICLE VIOLATIONS

The reduced amount listed below can be accepted for first offense non-out-of-service equipment violations, but only if the defendant submits proof that the repairs were made and submits a Certification of Repair and Plea of Guilty that is acceptable to the court.

49 C.F.R.	Pursuant to Federal Regulation as Adopted and Incorporated by Reference at N.J.A.C. 13:60-2	Reduced Amount
393.9	Inoperable lamps	\$56
393.11	Improper lamps/reflectors	\$56
393.13	Missing or improper reflective tape/sheeting on trailer(s)	\$56
393.17	Missing or improper lamps/reflectors on vehicle in tow	\$56
393.19	Missing or inoperable front turn signal	\$56
393.20	Missing or improperly mounted clearance lamps	\$56
393.24	Missing or improperly mounted/aimed head light lamps	\$56
393.25	Inoperable or obscured lamp other than head lamps	\$56
393.26	Improper mounting/specifications of reflectors	\$56
393.28	Missing or improper wiring protection	\$56
393.30	Improper battery installation	\$56
393.32	Improper electrical connections	\$56
393.33	Improper wiring installation	\$56
393.41	Missing or inoperable parking brake system	\$56
393.42	< 20% of brakes missing or defective	\$56
393.45	Unsecured break tube or hose	\$56
393.46	Missing/defective brake tube connection	\$56
393.47	< 20% of brakes with inadequate brake lining	\$56
393.48	< 20% of brake limiting device inoperative	\$56
393.51	Missing/defective brake warning device	\$56
393.53	Failure to have automatic brake adjustment system	\$56
393.60	Improper window or windshield glazing	\$56
393.61(a)	Improper or missing side window	\$56
393.62	Obstructed windows	\$56

49 C.F.R. **Pursuant to Federal Regulation as Adopted and
Incorporated by Reference at N.J.A.C. 13:60-2** **Reduced
Amount**

393.65	Missing fuel tank cap	\$56
393.70	Missing safety chain or cable	\$56
393.75	Worn tires not on steering axle	\$56
393.78	Missing or inoperable windshield wiper	\$56
393.79	Missing or inoperable defroster	\$56
393.80	Missing or damaged rear vision mirror	\$56
393.82	Inoperable speedometer	\$56
393.83	Defective exhaust system	\$56
393.84	Improper floor condition	\$56
393.86	Non-compliance with rear impact guard or rear end protection	\$56
393.93	Missing or inoperable seat belts	\$56
393.95	Missing emergency/warning equipment	\$56
393.201	One < 1½ inch crack with side rail web or one < 1" crack in side rail bottom flange	\$56
393.203	Inoperable door on cab or body component	\$56
393.205	Missing/loose/broken lug nuts	\$56
393.207	< ¼ of leaf springs broken	\$56
393.209	Excessive play in steering wheel	\$56
396.5	Excessive oil or grease leak	\$56